CERTIFICATE OF APPROPRIATENESS

Applicant: Roger Nicholson, owner

Property: 7815 Santa Elena St, lot 4, block 22 in the Glenbrook Valley Subdivision. The property includes a

historic 2,602 square-foot, one-story wood-frame single-family residence, situated on a 5,000 square

foot (50' x 100') corner lot.

Significance: Contributing traditional ranch style residence, constructed circa 1956, located in the Glenbrook

Valley Historic District.

Proposal: Alteration – Door and Windows:

The applicant proposes to replace the original door and the original aluminum windows with

aluminum windows by Don Young:

 Replace existing original windows for the following reasons: 66 years old, are single pane and not very energy efficient

Installation of Don Young aluminum windows with bronze finish

• Double pane, low e, and matching lite pattern

• Installation of new door and side lite that will match with the existing side lite

Removal of existing door

Installation of mid-century modern door with side lite matching glass in new door

See enclosed detailed project description and application materials for further details.

Public Comment: No public comment received.

Civic Association: Received comment in support of windows and door.

Recommendation: Denial - Does not meet criteria 5 and 6.

HAHC Action: -

ITEM ##

April 21, 2022 HPO File No. 2022_0033 Dr Glenbrook Valley

APPROVAL CRITERIA

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS


Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
\boxtimes			(1)	The proposed activity must retain and preserve the historical character of the property;
\boxtimes			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
		\boxtimes	(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
\boxtimes			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment;
			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site; The existing, historic aluminum windows are in good condition. These can be restored through ordinary maintenance and repair.
			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale; The scale of the Don Young windows does not match that of the existing windows. The proposed door is not visually compatible to the type of home.
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements;
\boxtimes			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area

Glenbrook Valley

PROPERTY LOCATION

GLENBROOK VALLEY HISTORIC DISTRICT



INVENTORY PHOTO



CURRENT PHOTO



Glenbrook Valley

Site Visit – Feb. 2, 2022 (Photos Taken By Staff) Front Door & Side Light







Glenbrook Valley




























PROPOSED REPLACEMENT DOOR





PROPOSED REPLACEMENT WINDOW





Energy Savings, Solar Control And Noise Protection

Single Hung WINDOWS

- 3/4" insulated glass provides year round energy savings and an excellent sound barrier to outside noise.
- Bottom sash tilts inward for safe and convenient cleaning.
- Continuous interlock provides a tighter seal greatly reducing the amount of dust and pollen entering your home.
- Patented Allerguard®
 Weather-stripping virtually
 eliminates air, dust and water from
 entering your home. .03 CFM
 Air infiltration rate.
- Metal spiral balances for dependable smooth trouble free operation.
- Child resistant tilt-in latches for added safety.
- Powder coat paint finish for a tough, durable smooth finish. Available in white, bronze, tan, and Silver
- Polyurethane thermally broken sash and frame dramatically reduces heat and cold transfer. Helps minimize condensation.

Double Hung WINDOWS

- 7/e" insulated glass provides year round energy savings and an excellent sound barrier to outside noise.
- Wrap around marine glazing blocks out cold air and water infiltration, and easily replaces in the event of glass breakage.
- Both sashes can ventilate or tilt-in for safe and convenient cleaning from inside your home. No need to clean from dangerous ladders.
- Interlocking meeting rails for tighter seal and added security
- Patented Allerguard®
 Weather-stripping virtually
 eliminates air, dust and water from
 entering your home.
- Metal spiral balances for dependable smooth trouble free operation.
- Child resistant tilt-in latches for added safety.
- Powder coat paint finish for a tough, durable smooth finish. Available in white, bronze, and tan.
- Polyurethane thermally broken sash and frame dramatically reduces heat and cold transfer. Helps minimize condensation.

LC-50 Commercially Rated 2³/₄" Main Frame Depth LC-30 Commercially Rated 3¹/₄" Main Frame Depth

All Covered Under Limited



Lifetime Warranty.




20821-D Eva St. #60 Montgomery, TX 77356 (281) 444-2299 UltraWindows.net

Customer Name Proposal Date Window Specified Glass Specified Frame Color Grids

Roger Nicholson February 7, 2022 Don Young 8200 series aluminum double pane with Low-E366/Argon bronze flat - between the glass

	Room	Quantity	Width	<u>Height</u>	<u>Glass</u>	<u>Grids</u>	<u>Style</u>
A	living room	1	144	80		none	patio door
В	breakfast	2	32	80		none	full view door
C	breakfast	2	36	48		2/2	single hung
D	bath	1	26	32		2/2	single hung
Ε	kitchen	1	38	38		2/2	single hung
F	piano	3	36	60		2/2	single hung
G	dining room	3	36	60		2/2	single hung
Н	guest 1	3	36	36		2/2	single hung
I	hall bath	1	38	38		2/2	single hung
J	guest 2	3	36	36		2/2	single hung
K	master	1	96	80		none	patio door
L	master	1	112	22		0 x 2	3 lite slider
M	master bath	1	38	38		2/2	single hung
		23					



CERTIFICATE OF APPROPRIATENESS



WINDOW	WORKSH	EET
--------	--------	-----

EXISTING WINDOW SCHEDULE								
Window	Material	Lite Pattern	Style	Dimensions	Recessed/Inset	Original/ Replacement	Existing to Remain	
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No	
FR	Aluminum	4		(6) 38 x 60	Recessed	Original	No	
FL	Aluminum	4		(6) 36 x 36	Recessed	Original	No	
SKS	Aluminum	4		(1) 38 x 38	Recessed	Original	No	
SBA	Aluminum	4		(2) 36 X 44	Recessed	Original	No	

DAMAGE TO EXISTING WINDOWS						
Window	Describe Damage					
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken					
FR	Front of House Right side of front door, Old, drafty and noisy					
FL	Front of House Left side of front door, Old, drafty and noisy					
SKS	Side of House Kitchen Sink, Old, drafty and noisy					
SBA	Side of House Breakfast Area, Old, drafty and noisy					

PROPOSED WINDOW SCHEDULE									
Window	Material	Lite	Style	Dimensions	Recessed/	Brand/	Other		
		Pattern			Inset	Vendor			
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Plygem			
FR	Aluminum	4		(6) 38 x 60	Recessed	Don Young Company			
FL	Aluminum	4		(6) 36 x 36	Recessed	Don Young Company			
SKS	Aluminum	4		(1) 38 x 38	Recessed	Don Young Company			
SBA	Aluminum	4		(2) 36 x 44	Recessed	Don Young Company			