

# **Incident Update**

## Houston Fire Department

### houstonfire.org

#### FOR IMMEDIATE RELEASE

DATE: December 19, 2016 1:09:47 PM CST

# APARTMENT FIRE IN SOUTH HOUSTON

## No Injuries Reported

The Houston Fire Department reminds citizens when using supplemental beating sources to take the fol		on Fire Department reminds citizens when using supplemental beating sources to take the follow
	Details:	Eight occupants were displaces, the American Red Cross and the on-site management company are assisting with occupant relocation.
	Cause:	Malfunctioning Heating Unit
	Damage:	Significant smoke visible by initial units.
	Injuries:	None Reported
	Where:	9220 Nathaniel St. Houston TX 77075 - Cabo San Lucas Apartments
	When:	December 19, 2016 at 11:13 a.m. Fire was declared under control 11:52 a.m
	What:	Apartment Fire in South Houston.

The Houston Fire Department reminds citizens when using supplemental heating sources to take the following precautions:

• Make sure you have a working smoke alarm.

- Never leave children unattended in a room with a space heater
- Keep all combustible materials, including yourself at least 3 feet from the heater
- Open face heaters should have a screen
- Don't use extension cords for the heater.
- Provide ventilation to prevent carbon monoxide poisoning
- Inspect heating units annually by a qualified service technician. Don't wait for cold weather!
- Vent pipes must exhaust to the outside!
- If your flame is not blue, it is not burning properly. It is producing Carbon Monoxide, Turn it off.
- Use flexible metal tubing with threaded ends to connect the heater to the gas valve.
- Use soapy water to check all connections and valves for leaks. NEVER use a match to test for a gas leak!
- Look for the American Gas Association label and follow the manufacturer's recommendations

### Contact:

Public Affairs Media Line: 832.394.6630





View this document online City of Houston City of Houston - Newsroom - www.houstongovnewsroom.org Visit this link to unsubscribe